L Number	Hits	Search Text	DB	Time stamp
1	1126	turning adj process	USPAT; US-PGPUB; EPO; JPO	2004/06/14 03:51
2	53875	helix	USPAT; US-PGPUB; EPO; JPO	2004/06/14 03:51
3	41434	cutting adj tool	USPAT; US-PGPUB; EPO; JPO	2004/06/14 03:51
4	843416	computer	USPAT; US-PGPUB; EPO; JPO	2004/06/14 03:52
5	1	(turning adj process) and helix and (cutting adj tool) and computer	USPAT; US-PGPUB; EPO; JPO	2004/06/14 03:57
6	216	82/1.11 and computer	USPAT; US-PGPUB; EPO; JPO	2004/06/14 03:58
7	9	82/1.11 and computer and helix	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:01
8	1493795	depth w2 cut	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:01
9	9	(82/1.11 and computer and helix) and (depth w2 cut)	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:02
10	7095	helix and computer and (depth w2 cut)	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:02
12	0	82/47 and (helix and computer and (depth w2 cut))	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:03
13	1	82/118 and (helix and computer and (depth w2 cut))	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:03
11	9	82/1.11 and (helix and computer and (depth w2 cut))	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:15

C:\APPS\east\workspaces\default2.wsp

L Number	Hits	Search Text	DB	Time stamp
1	1	"5788435"	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:30
2	1	measuring and "5788435"	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:31
4	38058	li and signal	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:32
5	1	"5788435" and signal	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:32
6	0	"5788435" and gauging	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:32
7	0	"5788435" and gauge	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:33
8	0	"5788435" and feedback	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:33
9	0	bluing adj gauge	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:36
10	4	bluing adj test	USPAT; US-PGPUB; EPO; JPO	2004/06/14 04:36

C:\APPS\east\workspaces\default2.wsp